Studying the Positioning Accuracy

# **Studying the Positioning Accuracy**

### **Causes of Error in the Positioning Accuracy**

The causes of error in the positioning accuracy include the lead angle accuracy, the axial clearance and the axial rigidity of the feed screw system. Other important factors include the thermal displacement from heat and the orientation change of the guide system during traveling.

### Studying the Lead Angle Accuracy

It is necessary to select the correct accuracy grade of the Ball Screw that satisfies the required positioning accuracy from the Ball Screw accuracies (Table1 on **Δ15-12**). Table23 on **Δ15-56** shows examples of selecting the accuracy grades by the application.

### **Studying the Axial Clearance**

The axial clearance is not a factor of positioning accuracy in single-directional feed. However, it will cause a backlash when the feed direction is inversed or the axial load is inversed. Select an axial clearance that meets the required backlash from Table10 and Table13 on **Δ15-19**.



Applications		Shaft	Accuracy grades							
			C0	C1	C2	C3	C5	C7	C8	C10
NC machine tools	Lathe	Х								
		Z								
	Machining center	XY								
		Z								
	Drilling machine	XY								
		Z								
	Jig borer	XY								
		Z								
	Surface grinder	Х								
		Y								
		Z								
	Cylindrical grinder	Х								
		Z								
	Electric discharge machine	XY								
		Z								
	Electric discharge machine Wire cutting machine	XY								
		Z								
		UV								
	Punching press	XY								
	Laser beam machine	Х								
		Z								
	Woodworking machine									
General-purpose machine; ded		licated machine								
Industrial robot	Cartesian coordinate	Assembly								
		Other								
	Vertical articulated type	Assembly								
		Other								
	Cylindrical coordinate									
Semiconductor manufacturing machine	Photolithography machine									
	Chemical treatment machine									
	Wire bonding machine									
	Prober									
	Printed circuit board drilling machine									
	Electronic component inserter									
3D measuring instrument										
Image processing machine										
Injection molding machine										
Office equipment										

A15-56 THK

Table23 Examples of Selecting Accuracy Grades by Application

Studying the Positioning Accuracy

### Studying the Axial Clearance of the Feed Screw System

Of the axial rigidities of the feed screw system, the axial rigidity of the screw shaft fluctuates according to the stroke position. When the axial rigidity is large, such change in the axial rigidity of the screw shaft will affect the positioning accuracy. Therefore, it is necessary to take into account the rigidity of the feed screw system ( $\blacksquare 15-51$  to  $\blacksquare 15-54$ ).

Example: Positioning error due to the axial rigidity of the feed screw system during a vertical transfer



[Conditions] Transferred weight: 1,000 N; table weight: 500 N Ball Screw used: model BNF2512–2.5 (screw-shaft thread minor diameter d<sub>1</sub> = 21.9 mm) Stroke length: 600 mm (L=100 mm to 700 mm) Screw shaft mounting type: fixed-supported

#### [Consideration]

The difference in axial rigidity between L = 100 mm and L = 700 mm applied only to the axial rigidity of the screw shaft.

Therefore, positioning error due to the axial rigidity of the feed screw system equals to the difference in the axial displacement of the screw shaft between L = 100 mm and L = 700 mm.



[Axial Rigidity of the Screw Shaft (see A15-51 and A15-52)]

$$K_{s} = \frac{A \cdot E}{1000L} = \frac{376.5 \times 2.06 \times 10^{5}}{1000 \times L} = \frac{77.6 \times 10^{3}}{L}$$
$$A = \frac{\pi}{4} d_{1}^{2} = \frac{\pi}{4} \times 21.9^{2} = 376.5 \text{ mm}^{2}$$
$$E = 2.06 \times 10^{5} \text{ N/mm}^{2}$$

(1) When L = 100 mm

$$K_{s_1} = \frac{77.6 \times 10^3}{100} = 776 \text{ N/}\mu\text{m}$$

(2) When L = 700mm

$$K_{s_2} = \frac{77.6 \times 10^3}{700} = 111 \text{ N/}\mu\text{m}$$

#### [Axial Displacement due to Axial Rigidity of the Screw Shaft]

(1) When L = 100 mm

$$\delta_1 = \frac{Fa}{K_{s1}} = \frac{1000 + 500}{776} = 1.9 \ \mu m$$

(2) When L = 700mm

$$\delta_2 = \frac{Fa}{K_{S2}} = \frac{1000 + 500}{111} = 13.5 \ \mu m$$

[Positioning Error due to Axial Rigidity of the Feed Screw System]

Positioning accuracy= $\delta_1$ - $\delta_2$ =1.9-13.5 =-11.6  $\mu m$ 

Therefore, the positioning error due to the axial rigidity of the feed screw system is 11.6  $\mu$ m.



Studying the Positioning Accuracy

### Studying the Thermal Displacement through Heat Generation

If the temperature of the screw shaft increases during operation, the screw shaft is elongated due to heat thereby to lower the positioning accuracy. The expansion and contraction of the screw shaft is calculated using the equation (43) below.

### $\Delta \boldsymbol{\ell} = \boldsymbol{\rho} \times \Delta \mathbf{t} \times \boldsymbol{\ell} \quad \dots \dots \quad (43)$

- $\Delta \ell$  : Axial expansion/contraction of the screw shaft (mm)
- $\rho$  : Thermal expansion coefficient (12×10<sup>-6</sup>/°C)
- $\Delta t$  : Temperature change in the screw shaft (°C)
- $\ell$  : Effective thread length (mm)

Thus, if the temperature of the screw shaft increases by 1°C, the screw shaft is elongated by 12  $\mu$ m per meter. Therefore, as the Ball Screw travels faster, the more heat is generated. So, as the temperature increases, the positioning accuracy lowers. Accordingly, if high accuracy is required, it is necessary to take measures to cope with the temperature increase.

#### [Measures to Cope with the Temperature Rise]

- Minimize the Heat Generation
- Minimize the preloads on the Ball Screw and the support bearing.
- Increase the Ball Screw lead and reduce the rotational speed.
- Select a correct lubricant. (See Accessories for Lubrication on A24-2.)
- Cool the circumference of the screw shaft with a lubricant or air.

#### • Avoid Effect of Temperature Rise through Heat Generation

Set a negative target value for the reference travel distance of the Ball Screw.
 Generally, set a negative target value for the reference travel distance assuming a temperature increase of 2°C to 5°C by heat.
 (0.02 mm to 0.06 mm/m)

(–0.02 mm to –0.06 mm/m)

Preload the shaft screw with tension. (See Fig.10 of the structure on 
15-29.)



## Studying the Orientation Change during Traveling

The lead angle accuracy of the Ball Screw equals the positioning accuracy of the shaft center of the Ball Screw. Normally, the point where the highest positioning accuracy is required changes according to the ball screw center and the vertical or horizontal direction. Therefore, the orientation change during traveling affects the positioning accuracy.

The largest factor of orientation change affecting the positioning accuracy is pitching if the change occurs in the ball screw center and the vertical direction, and yawing if the change occurs in the horizontal direction.

Accordingly, it is necessary to study the orientation change (accuracy in pitching, yawing, etc.) during the traveling on the basis of the distance from the ball screw center to the location where positioning accuracy is required.

Positioning error due to pitching and yawing is obtained using the equation (44) below.

#### $\mathbf{A} = \boldsymbol{\ell} \times \mathbf{sin} \boldsymbol{\theta} \cdots \cdots \cdots (44)$

A : Positioning accuracy due to pitching (or yawing) (mm)

 $\ell$ : Vertical (or horizontal) distance from the ball screw center (mm) (see Fig.18)

 $\boldsymbol{\theta}$  : Pitching (or yawing)

A15-60 10HK

(°)



Fig.18